



Hazards	electrical
Tools/Equipment	two pipe wrenches, wrenches, lock, chain and tag
Employee Group(s)	Facilities Management – Central Heating Plant

Required PPE:



Safety Shoes



Eye
Protection



Gloves

SAFE WORK PRACTICES

- Do not perform the procedure or operate the equipment until you have been appropriately trained and authorized to do so by your supervisor.
- Inspect required personal protective equipment (PPE) and replace if required.

PROCEDURE

1. Turn off power supply. Lock and tag.
2. Disconnect coupling to pump.
3. Unbolt motor.
4. Repair or replace motor.
5. Fasten motor back on and ensure bolts are tight.
6. Reconnect coupling to pump.
7. Remove lock and tag.
8. Turn power on.

NOTE: All PPE, tools and equipment shall be used in accordance with provincial OH&S legislation, manufacturer's specifications, applicable standards and codes of practice.