



Hazards	
Tools/Equipment	screw gun, paint shaker
Employee Group(s)	Facilities Management - Carpentry

Required PPE:



Safety Shoes



Eye
Protection

SAFE WORK PRACTICES

- Do not perform the procedure or operate the equipment until you have been appropriately trained and authorized to do so by your supervisor.
- Inspect required personal protective equipment (PPE) and replace if required.
- Use latex paints only, gallon only, no spray cans, no compressed gas containers.

PROCEDURE

1. Open the lid.
2. Install paint gallon in the container and clamp properly.
3. Close the protective cover.
4. Turn on the switch.
5. Do not leave unattended.
6. Turn mixer off.
7. Open protective cover.
8. Unplug from the outlet after every use.

NOTE: All PPE, tools and equipment shall be used in accordance with provincial OH&S legislation, manufacturer's specifications, applicable standards and codes of practice.